

Major repairs to Portsea beach seawall

Stakeholder Update, 11 November 2019



Stakeholder update

The Department of Environment, Land, Water and Planning's major repairs to the sandbag seawall at Portsea front beach are in progress.

The contractor has filled approximately 20% of the sandbags, pictured above. Wave and weather conditions this week have delayed completion of the temporary rock bund that is required to protect the team carrying out repairs to the sandbag wall (pictured above whilst progress is shown below).



A reminder that pedestrian access to the pier will be maintained during the works. Beach access remains open until we start removing sandbags. Works are taking place Monday to Saturday each week and are expected to take three to four months.

